

BUILDING SAFETY CERTIFICATENo. 09/26Dated: 05-05-26

It is certified that the existing building Bal Mandir Senior Secondary School (Name of the building or premises) at Purab Palai Kishanganj BR (address) is having block (s)/Floor (s) as per details below:

Details of Block (s) in school	Block (01)	Block (02)	Block (03)	Block (04)	Block (05)	Block (06)
No. of Floor (s) in the Block	G + 2 (Administrative Block)	G + 3 (North Block)	G + 3 (West Block)	G + 1 (East Block)	-	-

The building owned/occupied by Bal Mandir Senior Secondary School (Name of the institute) have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers of PWD, Building Construction Department, Building Division Kishanganj (Name of department/Govt.) on 25.04.2026 (date of inspection) in the presence of Sri. Lalit Kumar Mittal, Tegharia Kishanganj (name and address of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 25.04.2026 for a period of 02 (Two) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. NA
2. NA
3. NA
4. NA

Issued on at by

*Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: _____

MR. A. Ansari

Name: _____

Er. Md. Rafique Alam Ansari
(Approved Structural Engineer)
Regd. No.-BR/UDHD/SE/23-0041
BIHAR

Designation: _____

Name & Address of Department/Office: _____

Ansari
Principal
Bal Mandir Sr. Sec. School
Kishanganj
Aff. No.-330009

Lalit Kumar Mittal
Director
Bal Mandir Sr. Sec. School
Kishanganj